

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

OBSERVATION REPORT - SITE INVENTORY NO. 1 6 3 1 2 1 0 0 0 1

E 1
6/10/85
144775

St. Clair

CO. - L.P.C.

Region # S

Date 0 7/2 3/8 5

Sauget

/ Sauget

(Location)

(Responsible Party)

Letter Sent (Yes or No)

Samples Taken: Yes () No (X)

Time: From 0 8 : 1 5 a m

Weather 68° Sunny Dry

Ground Water() Surface() Other()

To 1 0 : 0 0 a m

Photos Taken: Yes (5) No ()

Interviewed No one

Inspector P M M
(27) (29)

Previous Inspection 6/10/85

Previous Correspondence 4/3/85

Site Open: Yes() No(X)

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating ()

Landfill (X)

Storage ()

E.P.A. Permit ()

Temporarily Closed ()

Random Dump ()

Salvage ()

Variance ()

Closed Not Covered (X)

Other ()

A.C.D. ()

21(e) ()

Closed and Covered ()

Quantity Received Daily(1-6) 1

Board Order ()

Illegal (5) (X) 5
(31)

LPC 4 1/79 5,000

IMPROVED

SAME

DETERIORATED

I S or D S
(62)

GENERAL REMARKS: Areas A, B and C were walked and inspected - The photos taken on 3/28/85 and 6/10/85 were compared to the conditions observed this date - No significant change was observed - No active operations with regards to covering were taking place - One load of construction and demolition material was observed in the southern part of Area "B" - A name was obtained from several blank checks - A letter will be written to that company. No observable recent random dumping has occurred in Area "C". The area observed on June 10, 1985 in the extreme southern portion of Area "B" and determined to be the responsibility of Palwood, Inc. of St. Louis has been spread and leveled and the southern slope has been covered.

INTERVIEW:

RECEIVED

JUL 26 1985

IFPA-DOC

DIAGRAM:

